TECHNICAL ARTICLE



Mathematical modeling and fuzzy availability analysis for serial processes in the crystallization system of a sugar plant

Anil Kr. Aggarwal¹ · Sanjeev Kumar² · Vikram Singh²

Received: 29 April 2015/Accepted: 8 August 2016/Published online: 24 August 2016 © The Author(s) 2016. This article is published with open access at Springerlink.com

Abstract The binary states, i.e., success or failed state assumptions used in conventional reliability are inappropriate for reliability analysis of complex industrial systems due to lack of sufficient probabilistic information. For large complex systems, the uncertainty of each individual parameter enhances the uncertainty of the system reliability. In this paper, the concept of fuzzy reliability has been used for reliability analysis of the system, and the effect of coverage factor, failure and repair rates of subsystems on fuzzy availability for fault-tolerant crystallization system of sugar plant is analyzed. Mathematical modeling of the system is carried out using the mnemonic rule to derive Chapman–Kolmogorov differential equations. These governing differential equations are solved with Runge–Kutta fourth-order method.

Keywords Markov birth–death process · Fuzzy availability · Reliability · Crystallization system · Reliability · Fault-tolerant system

Anil Kr. Aggarwal anil1995@rediffmail.com; anilpalwal@gmail.com

Sanjeev Kumar getsan25@rediffmail.com

Vikram Singh singhvikram77@gmail.com

- H.No. D-27, 218/3, Aggarsain Vihar (Sarai Pukhta), above old post office building, Palwal 121102, Haryana, India
- Department of Mechanical Engineering, YMCA University of Science and Technology, Sec. 6, Faridabad, Haryana, India

Introduction

The binary state assumption in conventional reliability theory is not extensively acceptable in various engineering problems. Since 1965, a higher importance in scientific environment has been given to fuzzy theory by Zadeh (1965), when he presented the basic concepts of fuzzy set theory. This has changed the basic scenario in reliability and concerned theories, because this theory can handle all the possible states that lie between a fully working state and a completely failed state. Thus, binary state assumption used in conventional reliability is replaced by fuzzy state assumption and this approach to the reliability is known as profust reliability. Though conventional reliability theory cannot be ignored, fuzzy reliability theory also needs to be considered along with it. The availability and reliability are the important performance parameters for industrial systems such as sugar mill, chemical industry, thermal power plant, paper plant, etc., and have major importance in real life situations, as the demand for product quality and system reliability has been increasing day by day.

This paper is organized as follows. The present section is the introductory type. Section 2 is concerned with materials and methods used, while Sect. 3 deals with the literature review. Section 4 is related with system description, notations and assumptions. Section 5 is devoted to mathematical modeling of the system. Section 6 is concerned with performance analysis of the system. Finally, some concrete conclusions have been presented in Sect. 7.



J Ind Eng Int (2017) 13:47-58

Materials and methods

Failure rate

The constant failure rate (β) is the ratio of the number of failures of a component in a given time to the total period of time the component was operating. It is expressed as the number of failures per unit hour.

Repair rate

The constant repair rate (μ) is the ratio of the number of repairs of a component in a given time to the total period of time the component was being repaired. It is expressed as the number of repairs per unit hour.

Fuzzy availability

Kumar and Kumar (2011) stated a fuzzy probabilistic semi-Markov model $\{(S_n, T_n), n \in N\}$ consisting of 'n' states together with transition time.

Let $U = \{S_1, S_2, ..., S_n\}$ denote the universe of discourse. On this universe, we define a fuzzy success state S, $S = \{(S_i, \mu_s(S_i); i = 1, 2, 3, ..., n\}$, and a fuzzy failure state F, $F = \{(S_i, \mu_s(S_i); i = 1, 2, 3, ..., n\}$,

where μ_s (S_i) and μ_F (S_i) are trapezoidal fuzzy numbers, respectively. The fuzzy availability of the crystallization system is defined as;


$$A(t) = \sum_{1}^{6} \mu s (Si) Pi(t).$$

Fault-tolerant system

A system is known to be fault tolerant, if it can tolerate some faults and function successfully even in the presence of these faults. It is generally achieved by using redundancy concepts. Automatic recovery and reconfiguration mechanism (detection, location and isolation) plays a crucial role in implementing fault tolerance, because an uncovered fault may lead to a system or subsystem failure even when adequate redundancy exists. Hence, a system subjected to imperfect fault coverage (also known as coverage factor) may fail prior to the exhaustion of redundancy due to uncovered component failures.

Coverage factor

Kumar and Kumar (2011) stated that the probability of successful reconfiguration operation of a fault-tolerant system is defined as a coverage factor. It is denoted by 'c'



Markov process

The continuous-time discrete-state Markov process models are used for describing the behavior of repairable systems in reliability studies as stated by Dhillion and Singh (1981) and Balaguruswamy (1984). The birth-and-death process is a special case of continuous-time Markov process; it is characterized by the birth rate (μ) and death rate (β) and it is assumed that the birth-and-death events are independent of each other. When a birth, i.e., repair occurs, the process goes from state i to state i+1. Similarly, when death, i.e., failure occurs, the process goes from state i to state i-1.

According to Markov, if $P_1(t)$ represents the probability of zero occurrences in time t, the probability of zero occurrences in time $(t + \Delta t)$ is given by the equation

$$P_1(t + \Delta t) = (1 - \beta t) P_1(t).$$
 (i)

Similarly,

$$P_2(t + \Delta t) = \mu \Delta t P_1(t) + (1 - \beta \Delta t) P_2(t).$$
 (ii)

The equation (ii) shows that the probability of one occurrence in time $(t + \Delta t)$ is composed of two units:

- (i) probability of zero occurrences in time t multiplied by the probability of one occurrence in time interval Δt and
- (ii) probability of one occurrence in time t multiplied by the probability of no occurrences in the interval Δt .

Literature review

The performance of an industrial system can be measured using several techniques as mentioned in the literature. Some of the techniques which are widely used are: event tree, fault tree analysis (FTA), reliability block diagrams (RBDs), Petri nets (PNs) and Markovian approach, as stated by Garg and Sharma (2012) and Renganathan and Bhaskar (2011). Garg and Sharma (2011) used the concept of fuzzy set theory to represent the failure and repair data and analyzed the behavior of the system using various reliability indices. These indices include failure rate, repair time, mean time between failures (MTBF), expected number of failures (ENOF) and availability and reliability of the system. Kumar et al. (2007) analyzed the reliability





of a non-redundant robot using fuzzy lambda-tau methodology. Singer (1990) developed a new methodology to find out various reliability parameters using fuzzy set approach and fault tree in which the failure rate and repair time were represented using triangular fuzzy numbers (TFN). Cheng and Mon (1993) used the confidence interval for analyzing the fuzzy system reliability. Chen (1994) presented a new method for analyzing system reliability using fuzzy number arithmetic operations. Knezevic and Odoom (2001) proposed a new methodology by making use of Petri nets (PNs) instead of fault trees. Arora and Kumar (1997) analyzed the availability for the coal handling system in the paper plant. Biswas and Sarkar (2000) studied the availability of a system maintained through several imperfect repairs before a replacement or a perfect repair. Jain (2003) discussed the N-policy for a redundant repairable system with an additional repairman. Singh et al. (2005) analyzed a three-unit standby system of water pumps in which two units were operative simultaneously and the third one was a cold standby for an ash handling plant. You and Chen (2005) proposed an efficient heuristic approach for series–parallel redundant reliability problems. Cheng and Mon (1993) presented a method for fuzzy system reliability analysis by interval of confidence. Chen (1994) presented a method for fuzzy system reliability analysis using fuzzy number arithmetic operations. Cai (1996) stated that the fuzzy reliability can be physically interpreted as the probability that no substantial performance deterioration occurs in a predefined time interval. Chen (2003) presented a new method for analyzing the fuzzy system reliability based on vague sets. Taheri and Zarei (2011) investigated the Bayesian system reliability assessment in a vague environment. Kumar and Yadav (2012) analyzed the fuzzy system reliability using different types of intuitionistic fuzzy numbers (IFNs) instead of the classical probability distribution for the components. Blischke and Murthy (2003) suggested that the failure of the component or system cannot be prevented completely, but can be minimized. Sharma and Khanduja (2013) discussed the performance evaluation and availability analysis of a feeding system of a sugar plant. Dhople et al. (2014) proposed a framework to analyze the Markov reward models, which are commonly used in the system performability analysis. Doostparast et al. (2014) planned a reliability-based periodic preventive maintenance (PM) for a system with deteriorating components. Shakuntla et al. (2011) discussed the availability analysis for a pipe manufacturing industry using supplementary variable technique. Katherasan et al. (2013) optimized the welding parameters for the flux cored arc welding process using the genetic algorithm and simulated annealing. Natarajan et al. (2013) proposed a model that would facilitate the infusing of quality and reliability in new products by blending the six sigma concept and the new product development (NPD) process. Yuan and Meng (2011) assumed the exponential distribution of working and repair time for a warm standby repairable system consisting of two dissimilar units and one repairman. Zhang and Mostashari (2011) proposed a method to assess the reliability of the system with continuous distribution of component states. This method is useful when we do not have enough knowledge on the component states and related probabilities. Zoulfaghari et al. (2014) presented a new mixed integer nonlinear programming (MINLP) model to analyze the availability optimization of a system with a given structure, using both repairable and non-repairable components simultaneously.

The literature revealed that the methods used by the authors involve complex computations, and the problem of determining long-run availability and reliability of the system based on conventional reliability has been extensively studied in the literature. In this paper, an advance numerical method, i.e., Runge–Kutta fourth-order method is used for fuzzy availability analysis for the crystallization system of a sugar plant. The required data are collected from the maintenance history sheets and by discussion with the maintenance personnel of the sugar plant situated at South of Haryana, India.

In the process of manufacturing of sugar, initially the sugarcane is fed through the conveyor and cutters to cut into small pieces. These small pieces of sugarcane are passed through the crushing system to get raw sugarcane juice and bagasse is left for the feeder or fodder. The process of refining raw sugarcane juice is performed as it contains fibers, mud and other impurities. The mud present in the sugarcane juice is separated by the sulfonation process, while the soluble and insoluble impurities present in the cane juice get further separated by heating the cane juice in boilers to about 68 °C. The juice gets concentrated by further heating to about 102 °C. The crystalline sugar is obtained from the concentrated juice by the crystallization process. The sugar plant comprises large complex engineering systems arranged in series or parallel, or a combination of both. Some of these systems are for feeding, crushing, refining, evaporation, steam generation, crystallization, etc., in which the crystallization system is one of the most important.

System description, notations and assumptions

System description

The crystallization system comprises the following three subsystems with series or parallel configurations as shown in Fig. 1.






Fig. 1 Schematic flow diagram of the crystallization system of a sugar plant with standby units

- (i) Subsystem A (crystallization): It consists of two units connected in parallel, one operative and the other in a cold standby state. The complete failure of the system will occur when more than one unit fail at a time.
- (ii) Subsystem B (centrifugal pump): It consists of three units connected in parallel and complete failure of the system will occur when more than two units fail at a time.
- (iii) Subsystem C (sugar grader unit): It consists of a single unit connected in series. The complete failure of the system will occur when this subsystem fails at a time.

Notations

: Indicates that the system is in a full working state.

: Indicates that the system is in a standby state.

A, B and C	Indicates full working states of subsystems
A_1 , B_1 and B_2	Indicates that the subsystems A and
	B are working under cold standby
	states
a, b and c	Indicates the failed states of
	subsystems A, B and C, respectively
$\beta_{\rm i} = 1, 2, 3 \dots 6$	The constant failure rate of
	subsystems A, A ₁ , B, B ₁ , B ₂ and C,
	respectively
$\mu_i = 1, 2, 36$	The constant repair rate of
	subsystems A, A ₁ , B, B ₁ , B ₂ and C,
	respectively
c	Coverage factor (its value lies
	between 0 and 1)
P_1, P_2, P_3, P_4, P_5	Fuzzy availability of the system
and P_6	under states 1, 2, 3, 4, 5 and 6,

respectively

 $P_{\rm j}$ (t), j = 1, 2, 3...17

The probability that the system is in the *j*th state at time t and p' represents its derivative with respect to time (t).

Assumptions

- The failure and repair rates are statistically independent of each other and there are no simultaneous failures among the subsystems as stated by Sharma and Khanduja (2013).
- There are sufficient repair or replacement facilities and a repaired system is as good as new, performance-wise, as stated by Ebeling (2001).

Mathematical modeling of the system

The mathematical modeling of the crystallization system is carried out using the mnemonic rule for the three subsystems and the Chapman–Kolmogorov differential equations are developed. According to this rule, the derivative of the probability of every state is equal to the sum of all probability flows which comes from other states to the given state minus the sum of all probability flows which goes out from the given state to the other states. The transition diagram (Fig. 2) depicts a simulation model showing all the possible states of the feeding system.

The equations for fuzzy availability for the crystallization system are derived as follows.

The mathematical Eqs. (1) to (17) are developed for each state, one by one, for 17 states of the transition diagram (Fig. 2).








Fig. 2 Transition diagram of the crystallization system of a sugar plant

$$P'_{1}(t) = -X_{1}P_{1}(t) + \mu_{1}P_{2}(t) + \mu_{3}P_{3}(t) + \mu_{6}P_{15}(t),$$
(1)

$$\begin{array}{lll} P_2'({\sf t}) & = & -X_2 P_2({\sf t}) \; + \; \beta_1 {\sf c} P_1({\sf t}) \; + \; \mu_2 P_{13}({\sf t}) \; + \; \mu_3 P_4({\sf t}) \\ & + \; \mu_6 P_{14}({\sf t}), \end{array}$$

$$P_3'(t) = -X_3P_3(t) + \mu_1P_4(t) + \beta_3cP_1(t) + \mu_4P_5(t) + \mu_6P_{16}(t),$$

$$P_4'(t) = -X_4 P_4(t) + \beta_1 c P_3(t) + \mu_1 P_{11}(t) + \beta_3 c P_2(t) + \mu_4 P_6(t) + \mu_6 P_{12}(t),$$

$$P_5'(t) = -X_5 P_5(t) + \mu_1 P_6(t) + \beta_4 c P_3(t) + \mu_5 P_7(t) + \mu_6 P_{17}(t).$$

(5)

$$P_6'(t) = -X_6 P_6(t) + \beta_1 c P_5(t) + \mu_1 P_{10}(t) + \beta_4 c P_4(t) + \mu_5 P_8(t) + \mu_6 P_9(t),$$

William Condition

where

$$X_1 = \beta_1 c + \beta_3 c + \beta_6 (1-c),$$

$$X_2 = \mu_1 + \beta_2(1-c) + \beta_3c + \beta_6(1-c),$$

$$X_3 = \beta_1 c + \mu_3 + \beta_4 c + \beta_6 (1-c),$$

$$X_4 = \mu_1 + \beta_1(1-c) + \mu_3 + \beta_4c + \beta_6(1-c),$$

$$X_5 = \beta_1 c + \mu_4 + \beta_5 (1-c) + \beta_6 (1-c),$$

$$X_6 = \mu_1 + \beta_2(1-c) + \mu_4 + \beta_5(1-c) + \beta_6(1-c)$$
. Similarly,

$$P_7'(t) + \mu_5 P_7(t) = \beta_5 (1 - c) P_5(t),$$
 (7)

$$P_8'(t) + \mu_5 P_8(t) = \beta_5 (1 - c) P_6(t),$$
 (8)

$$P_9'(t) + \mu_6 P_9(t) = \beta_6 (1 - c) P_6(t),$$
 (9)

$$P'_{10}(t) + \mu_1 P_{10}(t) = \beta_1 (1 - c) P_6(t),$$
 (10)

$$P'_{11}(t) + \mu_1 P_{11}(t) = \beta_1 (1 - c) P_4(t),$$
 (11)

$$P'_{12}(t) + \mu_6 P_{12}(t) = \beta_6 (1 - c) P_4(t),$$
 (12)

$$P'_{13}(t) + \mu_2 P_{13}(t) = \beta_2 (1 - c) P_2(t),$$
 (13)

$$P'_{14}(t) + \mu_6 P_{14}(t) = \beta_6 (1 - c) P_2(t),$$
 (14)

$$P'_{15}(t) + \mu_6 P_{15}(t) = \beta_6 (1 - c) P_1(t),$$
 (15)

$$P'_{16}(t) + \mu_6 P_{16}(t) = \beta_6 (1 - c) P_3(t),$$
 (16)

$$P'_{17}(t) + \mu_6 P_{17}(t) = \beta_6 (1 - c) P_5(t),$$
 (17)

with initial conditions:

$$P_{j}(0) = \begin{cases} 1, & \text{if } j = 1 \\ 0, & \text{if } j \neq 1 \end{cases}$$
 (18)

The system of differential Eqs. (1) to (17) with initial conditions given by Eq. (18) was solved by the Runge–Kutta fourth-order method. The numerical computations were carried out by taking that



52 J Ind Eng Int (2017) 13:47-58

Table 1 Effect of failure and repair rates of the crystallization subsystem on the fuzzy availability of the system

120	System coverage factor (c)	Days	Failure rate of crystallization (β_1)				Repair rate of crystallization (μ_1)			
120			0.0011	0.0012	0.0013	0.0014	0.018	0.023	0.028	0.033
$c = 0.4 \\ [180] $	c = 0	60	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335
$c = 0.2$ $\begin{array}{c ccccccccccccccccccccccccccccccccccc$		120	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623
$c = 0.2$ $\begin{array}{c} 300 \\ 360 \\ 360 \\ 0.6365 \\ 0.7711 \\ 0.7711 \\ 0.7717 \\ 0.7711 \\ 0.7710 \\ 0.6802 \\ 0.6860 \\ 0.6803 \\ 0.6800 \\ 0.6800 \\ 0.6809 \\ 0.6800 \\ 0.68$		180	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433
c = 0.2		240	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382
$\begin{array}{c} c = 0.2 \\ c = 0.2 \\$		300	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369
$c = 0.4$ $\begin{bmatrix} 120 & 0.7061 & 0.7058 & 0.7055 & 0.7052 & 0.7051 & 0.7058 & 0.7063 & 0.7067 \\ 180 & 0.6869 & 0.6866 & 0.6863 & 0.6860 & 0.6858 & 0.6866 & 0.6872 & 0.6876 \\ 240 & 0.6812 & 0.6809 & 0.6806 & 0.6803 & 0.6800 & 0.6809 & 0.6815 & 0.6820 \\ 360 & 0.6795 & 0.6792 & 0.6789 & 0.6786 & 0.6782 & 0.6792 & 0.6799 & 0.6803 \\ 360 & 0.6795 & 0.6792 & 0.6789 & 0.6786 & 0.6782 & 0.6792 & 0.6799 & 0.6803 \\ 360 & 0.6795 & 0.6782 & 0.6784 & 0.6781 & 0.6777 & 0.6787 & 0.6794 & 0.6798 \\ 360 & 0.8126 & 0.8121 & 0.8116 & 0.8110 & 0.8113 & 0.8121 & 0.8128 & 0.8133 \\ 120 & 0.7557 & 0.7551 & 0.7545 & 0.7538 & 0.7536 & 0.7551 & 0.7562 & 0.7570 \\ 180 & 0.7375 & 0.7356 & 0.7362 & 0.7355 & 0.7350 & 0.7368 & 0.7381 & 0.7390 \\ 240 & 0.7315 & 0.7309 & 0.7302 & 0.7296 & 0.7289 & 0.7309 & 0.7302 & 0.7303 \\ 360 & 0.7290 & 0.7283 & 0.7276 & 0.7269 & 0.7288 & 0.7289 & 0.7303 & 0.7313 \\ 360 & 0.7290 & 0.7283 & 0.8560 & 0.8544 & 0.8548 & 0.8560 & 0.8571 & 0.8580 \\ 120 & 0.8120 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 180 & 0.7965 & 0.7955 & 0.7945 & 0.7935 & 0.7968 & 0.7900 & 0.7921 & 0.7993 \\ 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7993 \\ 300 & 0.7891 & 0.7880 & 0.7875 & 0.7858 & 0.7900 & 0.7921 & 0.7993 \\ 300 & 0.7891 & 0.7880 & 0.7875 & 0.7855 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 240 & 0.7910 & 0.7880 & 0.7875 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ c = 0.8 & 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 240 & 0.8622 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8661 & 0.8666 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8694 \\ 240 & 0.8622 & 0.8607 & 0.8592 & 0.8578 & 0.8553 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 240 & 0.9483 & 0.9466 & 0.9447 & 0.9443 & 0.9433 & 0.9464 & 0.9506 & 0.9582 \\ 240 & 0.9483 & 0.9466 & 0.9447 & 0.9442 & 0.9410 & 0.9466 & 0.9505 & 0.9533 \\ 300 & 0.9482 & 0.9466 & 0.9447 & 0.9425 & 0.9401 & 0.9463 & 0.95$		360	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365
$c = 0.4$ $\begin{bmatrix} 180 & 0.6869 & 0.6866 & 0.6863 & 0.6860 & 0.6858 & 0.6866 & 0.6872 & 0.6876 \\ 240 & 0.6812 & 0.6809 & 0.6806 & 0.6803 & 0.6800 & 0.6809 & 0.6815 & 0.6820 \\ 300 & 0.6795 & 0.6792 & 0.6789 & 0.6786 & 0.6782 & 0.6792 & 0.6799 & 0.6803 \\ 360 & 0.6795 & 0.6792 & 0.6789 & 0.6786 & 0.6782 & 0.6797 & 0.6797 & 0.6794 & 0.6798 \\ 360 & 0.6780 & 0.6787 & 0.6784 & 0.6781 & 0.6777 & 0.6787 & 0.6794 & 0.6798 \\ 360 & 0.8126 & 0.8121 & 0.8116 & 0.8110 & 0.8113 & 0.8121 & 0.8128 & 0.8133 \\ 120 & 0.7557 & 0.7551 & 0.7545 & 0.7538 & 0.7536 & 0.7551 & 0.7562 & 0.7570 \\ 180 & 0.7315 & 0.7368 & 0.7362 & 0.7355 & 0.7350 & 0.7368 & 0.7381 & 0.7390 \\ 240 & 0.7315 & 0.7309 & 0.7302 & 0.7296 & 0.7289 & 0.7309 & 0.7322 & 0.7332 \\ 360 & 0.7296 & 0.7289 & 0.7283 & 0.7276 & 0.7268 & 0.7289 & 0.7303 & 0.7313 \\ 360 & 0.7296 & 0.7289 & 0.7283 & 0.7276 & 0.7268 & 0.7289 & 0.7303 & 0.7313 \\ 360 & 0.7296 & 0.7289 & 0.7283 & 0.7276 & 0.7268 & 0.7288 & 0.7297 & 0.7302 \\ 240 & 0.7910 & 0.7990 & 0.8552 & 0.8544 & 0.8548 & 0.8560 & 0.8571 & 0.8580 \\ 240 & 0.7910 & 0.7990 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7847 & 0.7880 & 0.7902 & 0.7914 \\ 240 & 0.7910 & 0.7990 & 0.7890 & 0.7889 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 240 & 0.7910 & 0.7890 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 240 & 0.7910 & 0.7880 & 0.7873 & 0.7853 & 0.7873 & 0.7895 & 0.7911 \\ 240 & 0.8622 & 0.8677 & 0.8593 & 0.8571 & 0.8515 & 0.8749 & 0.8747 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 \\ 240 & 0.8622 & 0.8607 & 0.8592 & 0.8578 & 0.8552 & 0.8546 & 0.8675 & 0.8693 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 240 & 0.9483 & 0.9466 & 0.9437 & 0.9443 & 0.9433 & 0.9446 & 0.9566 & 0.9582 \\ 240 & 0.9483 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9466 & 0.9447 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9505 \\ 240 & 0.9483 $	c = 0.2	60	0.7716	0.7713	0.7711	0.7708	0.7710	0.7713	0.7717	0.7719
$c=0.4$ $\begin{array}{c} 240 \\ 300 \\ 300 \\ 0.6795 \\ 0.6792 \\ 0.6789 \\ 0.6789 \\ 0.6786 \\ 0.6786 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6787 \\ 0.6782 \\ 0.6792 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6792 \\ 0.6792 \\ 0.6792 \\ 0.6789 \\ 0.6786 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6787 \\ 0.6782 \\ 0.6782 \\ 0.6782 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6782 \\ 0.6781 \\ 0.6781 \\ 0.6781 \\ 0.6782 \\ 0.7551 \\ 0.7556 \\ 0.7551 \\ 0.7552 \\ 0.7551 \\ 0.7552 \\ 0.7551 \\ 0.7552 \\ 0.7552 \\ 0.7552 \\ 0.7553 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7352$		120	0.7061	0.7058	0.7055	0.7052	0.7051	0.7058	0.7063	0.7067
$c = 0.4$ $\begin{array}{c} 300 \\ 360 \\ 0.6795 \\ 0.6792 \\ 0.6787 \\ 0.6787 \\ 0.6784 \\ 0.6781 \\ 0.6781 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6781 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6781 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6787 \\ 0.6798 \\ 0.7553 \\ 0.7553 \\ 0.7553 \\ 0.7553 \\ 0.7556 \\ 0.7551 \\ 0.7556 \\ 0.7557 \\ 0.7552 \\ 0.7552 \\ 0.7552 \\ 0.7553 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7356 \\ 0.7358 \\ 0.7381 \\ 0.7399 \\ 0.7302 \\ 0.7302 \\ 0.7302 \\ 0.7302 \\ 0.7303 \\ 0.7313 \\ 0.726 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.726 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.726 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.726 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.726 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7297 \\ 0.7303 \\ 0.7307 \\ 0.726 \\ 0.7289 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.726 \\ 0.7289 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.7268 \\ 0.7289 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.7297 \\ 0.7307 \\ 0.726 \\ 0.7289 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.7261 \\ 0.7283 \\ $		180	0.6869	0.6866	0.6863	0.6860	0.6858	0.6866	0.6872	0.6876
$c = 0.4$ $\begin{array}{c} 360 \\ 60 \\ 0.8126 \\ 0.8121 \\ 0.8121 \\ 0.8121 \\ 0.8121 \\ 0.8116 \\ 0.8110 \\ 0.8110 \\ 0.8113 \\ 0.8113 \\ 0.8121 \\ 0.8133 \\ 0.8121 \\ 0.8121 \\ 0.8133 \\ 0.8121 \\ 0.8133 \\ 0.8121 \\ 0.8133 \\ 0.8121 \\ 0.8128 \\ 0.8133 \\ 0.8121 \\ 0.8128 \\ 0.8133 \\ 0.8121 \\ 0.8128 \\ 0.8133 \\ 0.8121 \\ 0.8121 \\ 0.8128 \\ 0.8133 \\ 0.8133 \\ 0.8121 \\ 0.8121 \\ 0.8121 \\ 0.8123 \\ 0.8133 \\ 0.7556 \\ 0.7551 \\ 0.7552 \\ 0.7552 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7355 \\ 0.7350 \\ 0.7368 \\ 0.7368 \\ 0.7389 \\ 0.7309 \\ 0.7302 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7261 \\ 0.7289 \\ 0.7268 \\ 0.7289 \\ 0.7289 \\ 0.7268 \\ 0.7289 \\ 0.7289 \\ 0.7289 \\ 0.7268 \\ 0.7289 \\ 0.7268 \\ 0.8571 \\ 0.8580 \\ 0.8571 \\ 0.8580 \\ 0.8571 \\ 0.8580 \\ 0.8571 \\ 0.8580 \\ 0.8561 \\ 0.8591 \\ 0.8580 \\ 0.8591 \\ 0.8838 \\ 0.8990 \\ 0.7873 \\ 0.7852 \\ 0.7859 \\ 0.7868 \\ 0.7900 \\ 0.7921 \\ 0.7921 \\ 0.7937 \\ 0.7937 \\ 0.7850 \\ 0.7859 \\ 0.7868 \\ 0.7900 \\ 0.7921 \\ 0.7937 \\ 0.7850 \\ 0.7859 \\ 0.7868 \\ 0.7900 \\ 0.7921 \\ 0.7937 \\ 0.7941 \\ 0.8622 \\ 0.8677 \\ 0.8593 \\ 0.8572 \\ 0.8571 \\ 0.8580 \\ 0.7900 \\ 0.7921 \\ 0.7937 \\ 0.7945 \\ 0.7859 \\ 0.7847 \\ 0.7880 \\ 0.7900 \\ 0.7921 \\ 0.7941 \\ 0.9042 \\ 0.8622 \\ 0.8667 \\ 0.8661 \\ 0.8675 \\ 0.8593 \\ 0.8578 \\ 0.8562 \\ 0.8607 \\ 0.8661 \\ 0.8661 \\ 0.8665 \\ 0.8675 \\ 0.8593 \\ 0.8562 \\ 0.8607 \\ 0.8638 \\ 0.8665 \\ 0.8667 \\ 0.$		240	0.6812	0.6809	0.6806	0.6803	0.6800	0.6809	0.6815	0.6820
$\begin{array}{c} c = 0.4 \\ & \begin{array}{c} 60 \\ & 0.8126 \\ & 120 \\ & 0.7557 \\ & 0.7557 \\ & 0.7551 \\ & 0.7545 \\ & 0.7538 \\ & 0.7536 \\ & 0.7536 \\ & 0.7536 \\ & 0.7551 \\ & 0.7562 \\ & 0.7551 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7562 \\ & 0.7570 \\ & 0.7368 \\ & 0.7355 \\ & 0.7355 \\ & 0.7350 \\ & 0.7368 \\ & 0.7381 \\ & 0.7368 \\ & 0.7381 \\ & 0.7390 \\ & 0.7302 \\ & 0.7296 \\ & 0.7289 \\ & 0.7289 \\ & 0.7289 \\ & 0.7283 \\ & 0.7276 \\ & 0.7269 \\ & 0.7261 \\ & 0.7268 \\ & 0.7289 \\ & 0.7283 \\ & 0.7276 \\ & 0.7269 \\ & 0.7261 \\ & 0.7263 \\ & 0.7297 \\ & 0.7303 \\ & 0.7303 \\ & 0.7303 \\ & 0.7303 \\ & 0.7303 \\ & 0.7303 \\ & 0.7303 \\ & 0.7297 \\ & 0.7303 \\ & 0.7297 \\ & 0.7307 \\ & 0.7265 \\ & 0.8552 \\ & 0.8544 \\ & 0.8548 \\ & 0.8560 \\ & 0.8560 \\ & 0.8561 \\ & 0.8561 \\ & 0.8561 \\ & 0.8562 \\ & 0.8552 \\ & 0.8544 \\ & 0.8687 \\ & 0.8548 \\ & 0.8560 \\ & 0.8560 \\ & 0.8561 \\ & 0.8564 \\ & 0.8562 \\ & 0.8561 \\ & 0.8562 \\ & 0.8561 \\ & 0.7955 \\ & 0.7945 \\ & 0.7945 \\ & 0.7926 \\ & 0.7926 \\ & 0.7925 \\ & 0.7955 \\ & 0.7976 \\ & 0.7997 \\ & 0.7990 \\ & 0.7890 \\ & 0.7889 \\ & 0.7879 \\ & 0.7889 \\ & 0.7879 \\ & 0.7868 \\ & 0.7900 \\ & 0.7992 \\ & 0.7911 \\ & 0.7900 \\ & 0.7889 \\ & 0.7879 \\ & 0.7889 \\ & 0.7879 \\ & 0.7868 \\ & 0.7900 \\ & 0.7925 \\ & 0.7975 \\ & 0.7995 \\ & 0.7976 \\ & 0.7995 \\ & 0.799$		300	0.6795	0.6792	0.6789	0.6786	0.6782	0.6792	0.6799	0.6803
$c = 0.8$ $\begin{bmatrix} 120 & 0.7557 & 0.7551 & 0.7545 & 0.7538 & 0.7536 & 0.7551 & 0.7562 & 0.7570 \\ 180 & 0.7375 & 0.7368 & 0.7362 & 0.7355 & 0.7350 & 0.7368 & 0.7381 & 0.7390 \\ 240 & 0.7315 & 0.7309 & 0.7302 & 0.7296 & 0.7289 & 0.7309 & 0.7322 & 0.7332 \\ 300 & 0.7296 & 0.7289 & 0.7283 & 0.7276 & 0.7268 & 0.7289 & 0.7303 & 0.7313 \\ 360 & 0.7290 & 0.7283 & 0.7276 & 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ c = 0.6 & 60 & 0.8569 & 0.8560 & 0.8552 & 0.8544 & 0.8548 & 0.8560 & 0.8571 & 0.8580 \\ 120 & 0.8120 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 180 & 0.7965 & 0.7955 & 0.7945 & 0.7935 & 0.7926 & 0.7955 & 0.7976 & 0.7990 \\ 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7890 & 0.7879 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 26 = 0.8 & 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 300 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 360 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482$		360	0.6790	0.6787	0.6784	0.6781	0.6777	0.6787	0.6794	0.6798
$c = 0.6$ $\begin{bmatrix} 180 & 0.7375 & 0.7368 & 0.7362 & 0.7355 & 0.7350 & 0.7368 & 0.7381 & 0.7399 \\ 240 & 0.7315 & 0.7309 & 0.7302 & 0.7296 & 0.7289 & 0.7309 & 0.7322 & 0.7332 \\ 300 & 0.7296 & 0.7289 & 0.7283 & 0.7276 & 0.7268 & 0.7289 & 0.7303 & 0.7313 \\ 360 & 0.7290 & 0.7283 & 0.7276 & 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.7269 & 0.8560 & 0.8551 & 0.8544 & 0.8548 & 0.8560 & 0.8571 & 0.8580 \\ 0.8270 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 0.8270 & 0.8120 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 0.7270 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 0.7270 & 0.7891 & 0.7880 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 0.7270 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ 0.7270 & 0.8763 & 0.8749 & 0.8752 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ 0.8270 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 0.8270 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 0.8270 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 0.8270 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 0.8270 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 0.8280 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 0.940 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 0.940 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 0.9504 & 0.9504 & 0.9533 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 0.9504 & 0.99482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.$	c = 0.4	60	0.8126	0.8121	0.8116	0.8110	0.8113	0.8121	0.8128	0.8133
$c = 0.6$ $\begin{array}{c} 240 \\ 300 \\ 0.7315 \\ 0.7296 \\ 0.7289 \\ 0.7289 \\ 0.7283 \\ 0.7276 \\ 0.7269 \\ 0.7268 \\ 0.7268 \\ 0.7268 \\ 0.7288 \\ 0.7283 \\ 0.7276 \\ 0.7268 \\ 0.7268 \\ 0.7283 \\ 0.7261 \\ 0.7268 \\ 0.7283 \\ 0.7276 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7269 \\ 0.7261 \\ 0.7263 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.7267 \\ 0.7269 \\ 0.7261 \\ 0.7263 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7297 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7261 \\ 0.8580 \\ 0.8561 \\ 0.8544 \\ 0.8548 \\ 0.8560 \\ 0.8571 \\ 0.8087 \\ 0.8111 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8087 \\ 0.7995 \\ 0.7995 \\ 0.7995 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7995 \\ 0.7996 \\ 0.7997 \\ 0.7997 \\ 0.7911 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9901 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9911 \\ 0.9917 \\ 0.9934 \\ 0.9911 \\ 0.9917 \\ 0.9911 \\ 0.9917 \\ 0.9911 \\ 0.9917 \\ 0.9911 \\ 0.9917 \\ 0.9917 \\ 0.9918 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0.8794 \\ 0.8793 \\ 0.8794 \\ 0$		120	0.7557	0.7551	0.7545	0.7538	0.7536	0.7551	0.7562	0.7570
$c = 0.6$ $\begin{array}{c} 300 \\ 360 \\ 0.7296 \\ 0.7283 \\ 0.7283 \\ 0.7276 \\ 0.7269 \\ 0.7261 \\ 0.7269 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7313 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7261 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7261 \\ 0.7261 \\ 0.7261 \\ 0.7283 \\ 0.7297 \\ 0.7303 \\ 0.7303 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.7307 \\ 0.8580 \\ 0.8561 \\ 0.8091 \\ 0.8087 \\ 0.8111 \\ 0.8101 \\ 0.8087 \\ 0.8111 \\ 0.8101 \\ 0.8091 \\ 0.8087 \\ 0.8111 \\ 0.8087 \\ 0.8087 \\ 0.8111 \\ 0.8128 \\ 0.8142 \\ 0.7926 \\ 0.7955 \\ 0.7945 \\ 0.7935 \\ 0.7926 \\ 0.7926 \\ 0.7926 \\ 0.7925 \\ 0.7976 \\ 0.7990 \\ 0.7918 \\ 0.7900 \\ 0.7921 \\ 0.7937 \\ 0.7918 \\ 0.7808 \\ 0.7902 \\ 0.7918 \\ 0.7808 \\ 0.7902 \\ 0.7918 \\ 0.7808 \\ 0.7902 \\ 0.7918 \\ 0.7808 \\ 0.7902 \\ 0.7918 \\ 0.7808 \\ 0.7902 \\ 0.7918 \\ 0.7911 \\ 0.9047 \\ 0.9048 \\ 0.9048 \\ 0.9023 \\ 0.9011 \\ 0.9017 \\ 0.9047 \\ 0.9047 \\ 0.9017 \\ 0.9034 \\ 0.9047 \\ 0.8679 \\ 0.8671 \\ 0.8697 \\ 0.8592 \\ 0.8678 \\ 0.8572 \\ 0.8578 \\ 0.8562 \\ 0.8607 \\ 0.8539 \\ 0.8566 \\ 0.8617 \\ 0.8539 \\ 0.8566 \\ 0.8617 \\ 0.8639 \\ 0.8617 \\ 0.8639 \\ 0.8645 \\ 0.8617 \\ 0.8639 \\ 0.8645 \\ 0.8617 \\ 0.8639 \\ 0.8646 \\ 0.9447 \\ 0.9429 \\ 0.9410 \\ 0.9466 \\ 0.9504 \\ 0.9504 \\ 0.9504 \\ 0.9503 \\ 0.9534 \\ 0.9464 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9604 \\ 0.9443 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9604 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9604 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9604 \\ 0.9403 \\ 0.9463 \\ 0.9463 \\ 0.9463 \\ 0.9465 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0$		180	0.7375	0.7368	0.7362	0.7355	0.7350	0.7368	0.7381	0.7390
$c = 0.6$ $\begin{array}{c} 360 & 0.7290 & 0.7283 & 0.7276 & 0.7269 & 0.7261 & 0.7283 & 0.7297 & 0.7307 \\ 0.8560 & 0.8569 & 0.8560 & 0.8552 & 0.8544 & 0.8548 & 0.8560 & 0.8571 & 0.8580 \\ 120 & 0.8120 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 180 & 0.7965 & 0.7955 & 0.7945 & 0.7935 & 0.7926 & 0.7955 & 0.7976 & 0.7990 \\ 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7880 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ c = 0.8 & 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ c = 1.0 & 60 & 0.9561 & 0.9546 & 0.9531 & 0.9516 & 0.9523 & 0.9546 & 0.9566 & 0.9582 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 $		240	0.7315	0.7309	0.7302	0.7296	0.7289	0.7309	0.7322	0.7332
$c = 0.6 \\ \begin{array}{c} 60 \\ 0.8569 \\ 120 \\ 0.8120 \\ 0.8120 \\ 0.8111 \\ 0.8101 \\ 0.8091 \\ 0.8091 \\ 0.8087 \\ 0.8111 \\ 0.8128 \\ 0.8560 \\ 0.8571 \\ 0.8580 \\ 0.8511 \\ 0.8142 \\ 0.8142 \\ 0.8142 \\ 0.8142 \\ 0.8142 \\ 0.8091 \\ 0.8091 \\ 0.8087 \\ 0.8111 \\ 0.8128 \\ 0.8111 \\ 0.8128 \\ 0.8142 \\ 0.8142 \\ 0.8142 \\ 0.8925 \\ 0.7935 \\ 0.7926 \\ 0.7955 \\ 0.7976 \\ 0.7955 \\ 0.7976 \\ 0.7990 \\ 0.7890 \\ 0.7879 \\ 0.7868 \\ 0.7900 \\ 0.7879 \\ 0.7868 \\ 0.7900 \\ 0.7910 \\ 0.7900 \\ 0.7880 \\ 0.7870 \\ 0.7859 \\ 0.7879 \\ 0.7847 \\ 0.7880 \\ 0.7900 \\ 0.7910 \\ 0.7921 \\ 0.7900 \\ 0.7918 \\ 0.7873 \\ 0.7859 \\ 0.7847 \\ 0.7880 \\ 0.7902 \\ 0.7911 \\ 0.7880 \\ 0.7902 \\ 0.7911 \\ 0.7880 \\ 0.7902 \\ 0.7911 \\ 0.9017 \\ 0.9034 \\ 0.9049 \\ 0.9049 \\ 0.9049 \\ 0.9049 \\ 0.9062 \\ 0.8671 \\ 0.8774 \\ 0.8793 \\ 0.8561 \\ 0.8661 \\ 0.8661 \\ 0.8661 \\ 0.8661 \\ 0.8662 \\ 0.8607 \\ 0.8593 \\ 0.8578 \\ 0.8562 \\ 0.8607 \\ 0.8638 \\ 0.8659 \\ 0.8623 \\ 0.8645 \\ 0.8646 \\ 0.8639 \\ 0.8646 \\ 0.8646 \\ 0.8659 \\ 0.8646 \\ 0.8659 \\ 0.8658 \\ 0.8617 \\ 0.8639 \\ 0.8586 \\ 0.8617 \\ 0.8639 \\ 0.8586 \\ 0.8617 \\ 0.8639 \\ 0.8586 \\ 0.8617 \\ 0.8639 \\ 0.9481 \\ 0.9447 \\ 0.9429 \\ 0.9410 \\ 0.9466 \\ 0.9504 \\ 0.9504 \\ 0.9503 \\ 0.9534 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.90401 \\ 0.9463 \\ 0.9463 \\ 0.9464 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9644 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9641 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9403 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9644 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9403 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9641 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9403 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9463 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9403 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9463 \\ 0.9444 \\ 0.9425 \\ 0.9401 \\ 0.9403 \\ 0$		300	0.7296	0.7289	0.7283	0.7276	0.7268	0.7289	0.7303	0.7313
$c = 0.8$ $\begin{bmatrix} 120 & 0.8120 & 0.8111 & 0.8101 & 0.8091 & 0.8087 & 0.8111 & 0.8128 & 0.8142 \\ 180 & 0.7965 & 0.7955 & 0.7945 & 0.7935 & 0.7926 & 0.7955 & 0.7976 & 0.7990 \\ 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7880 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 0.9487 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0$		360	0.7290	0.7283	0.7276	0.7269	0.7261	0.7283	0.7297	0.7307
$c = 0.8$ $\begin{bmatrix} 180 & 0.7965 & 0.7955 & 0.7945 & 0.7935 & 0.7926 & 0.7955 & 0.7976 & 0.7990 \\ 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7880 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ c = 0.8$ $\begin{bmatrix} 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.$	c = 0.6	60	0.8569	0.8560	0.8552	0.8544	0.8548	0.8560	0.8571	0.8580
$\begin{array}{c} 240 & 0.7910 & 0.7900 & 0.7890 & 0.7879 & 0.7868 & 0.7900 & 0.7921 & 0.7937 \\ 300 & 0.7891 & 0.7880 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ c = 0.8 & 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ c = 1.0 & 60 & 0.9561 & 0.9546 & 0.9531 & 0.9516 & 0.9523 & 0.9546 & 0.9566 & 0.9582 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.$		120	0.8120	0.8111	0.8101	0.8091	0.8087	0.8111	0.8128	0.8142
$c = 0.8$ $\begin{array}{c} 300 & 0.7891 & 0.7880 & 0.7870 & 0.7859 & 0.7847 & 0.7880 & 0.7902 & 0.7918 \\ 360 & 0.7883 & 0.7873 & 0.7863 & 0.7852 & 0.7839 & 0.7873 & 0.7895 & 0.7911 \\ c = 0.8 & 60 & 0.9046 & 0.9034 & 0.9023 & 0.9011 & 0.9017 & 0.9034 & 0.9049 & 0.9062 \\ 120 & 0.8763 & 0.8749 & 0.8735 & 0.8721 & 0.8715 & 0.8749 & 0.8774 & 0.8793 \\ 180 & 0.8661 & 0.8646 & 0.8632 & 0.8618 & 0.8605 & 0.8646 & 0.8675 & 0.8697 \\ 240 & 0.8622 & 0.8607 & 0.8593 & 0.8578 & 0.8562 & 0.8607 & 0.8638 & 0.8659 \\ 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ c = 1.0 & 60 & 0.9561 & 0.9546 & 0.9531 & 0.9516 & 0.9523 & 0.9546 & 0.9566 & 0.9582 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9504 & 0.9533 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ \end{array}$		180	0.7965	0.7955	0.7945	0.7935	0.7926	0.7955	0.7976	0.7990
$c = 0.8$ $\begin{array}{c} 360 \\ 0.7883 \\ 0.7873 \\ 0.7873 \\ 0.7863 \\ 0.9046 \\ 0.9034 \\ 0.9023 \\ 0.9011 \\ 0.9017 \\ 0.9017 \\ 0.9034 \\ 0.9034 \\ 0.9049 \\ 0.9049 \\ 0.9062 \\ 0.8774 \\ 0.8793 \\ 0.8774 \\ 0.8793 \\ 0.8793 \\ 0.8794 \\ 0.8774 \\ 0.8793 \\ 0.8661 \\ 0.8661 \\ 0.8664 \\ 0.8632 \\ 0.8607 \\ 0.8593 \\ 0.8578 \\ 0.8562 \\ 0.8607 \\ 0.8592 \\ 0.8607 \\ 0.8592 \\ 0.8578 \\ 0.8563 \\ 0.8578 \\ 0.8563 \\ 0.8545 \\ 0.8592 \\ 0.8607 \\ 0.8638 \\ 0.8638 \\ 0.8645 \\ 0.8645 \\ 0.8659 \\ 0.8617 \\ 0.8639 \\ 0.8645 \\ 0.8617 \\ 0.8639 \\ 0.8645 \\ 0.9521 \\ 0.9466 \\ 0.9531 \\ 0.9516 \\ 0.9523 \\ 0.9546 \\ 0.9533 \\ 0.9479 \\ 0.9410 \\ 0.9466 \\ 0.9505 \\ 0.9503 \\ 0.9504 \\ 0.9503 \\ 0.9533 \\ 0.9464 \\ 0.9445 \\ 0.9426 \\ 0.9403 \\ 0.9403 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9503 \\ 0.9533 \\ 0.9534 \\ 0.9533 \\ 0.9544 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9534 \\ 0.9533 \\ 0.9544 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9544 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9503 \\ 0.9533 \\ 0.9534 \\ 0.9533 \\ 0.9544 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9664 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9664 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9503 \\ 0.9504 \\ 0.9533 \\ 0.9664 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9664 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9463 \\ 0.9464 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9664 \\ 0.9445 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9463 \\ 0.9464 \\ 0.9425 \\ 0.9401 \\ 0.9463 \\ 0.9463 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9504 \\ 0.9533 \\ 0.9504 \\ 0.9504 \\ 0.9504 \\ 0.9504 \\ 0.9504 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 \\ 0.9505 $		240	0.7910	0.7900	0.7890	0.7879	0.7868	0.7900	0.7921	0.7937
$c = 0.8 \\ \begin{array}{ccccccccccccccccccccccccccccccccccc$		300	0.7891	0.7880	0.7870	0.7859	0.7847	0.7880	0.7902	0.7918
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		360	0.7883	0.7873	0.7863	0.7852	0.7839	0.7873	0.7895	0.7911
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	c = 0.8	60	0.9046	0.9034	0.9023	0.9011	0.9017	0.9034	0.9049	0.9062
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		120	0.8763	0.8749	0.8735	0.8721	0.8715	0.8749	0.8774	0.8793
$\begin{array}{c} 300 & 0.8607 & 0.8592 & 0.8578 & 0.8563 & 0.8545 & 0.8592 & 0.8623 & 0.8645 \\ 360 & 0.8601 & 0.8586 & 0.8572 & 0.8557 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ c = 1.0 & 60 & 0.9561 & 0.9546 & 0.9531 & 0.9516 & 0.9523 & 0.9546 & 0.9566 & 0.9582 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ \end{array}$		180	0.8661	0.8646	0.8632	0.8618	0.8605	0.8646	0.8675	0.8697
$\begin{array}{c} 360 & 0.8601 & 0.8586 & 0.8572 & 0.8537 & 0.8539 & 0.8586 & 0.8617 & 0.8639 \\ 60 & 0.9561 & 0.9546 & 0.9531 & 0.9516 & 0.9523 & 0.9546 & 0.9566 & 0.9582 \\ 120 & 0.9497 & 0.9479 & 0.9461 & 0.9443 & 0.9433 & 0.9479 & 0.9513 & 0.9539 \\ 180 & 0.9485 & 0.9466 & 0.9447 & 0.9429 & 0.9410 & 0.9466 & 0.9505 & 0.9534 \\ 240 & 0.9483 & 0.9464 & 0.9445 & 0.9426 & 0.9403 & 0.9464 & 0.9504 & 0.9533 \\ 300 & 0.9482 & 0.9463 & 0.9444 & 0.9425 & 0.9401 & 0.9463 & 0.9504 & 0.9533 \\ \end{array}$		240	0.8622	0.8607	0.8593	0.8578	0.8562	0.8607	0.8638	0.8659
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		300	0.8607	0.8592	0.8578	0.8563	0.8545	0.8592	0.8623	0.8645
120 0.9497 0.9479 0.9461 0.9443 0.9433 0.9479 0.9513 0.9539 180 0.9485 0.9466 0.9447 0.9429 0.9410 0.9466 0.9505 0.9534 240 0.9483 0.9464 0.9445 0.9426 0.9403 0.9464 0.9504 0.9533 300 0.9482 0.9463 0.9444 0.9425 0.9401 0.9463 0.9504 0.9533		360	0.8601	0.8586	0.8572	0.8557	0.8539	0.8586	0.8617	0.8639
180 0.9485 0.9466 0.9447 0.9429 0.9410 0.9466 0.9505 0.9534 240 0.9483 0.9464 0.9445 0.9426 0.9403 0.9464 0.9504 0.9533 300 0.9482 0.9463 0.9444 0.9425 0.9401 0.9463 0.9504 0.9533	c = 1.0	60	0.9561	0.9546	0.9531	0.9516	0.9523	0.9546	0.9566	0.9582
240 0.9483 0.9464 0.9445 0.9426 0.9403 0.9464 0.9504 0.9533 300 0.9482 0.9463 0.9444 0.9425 0.9401 0.9463 0.9504 0.9533		120	0.9497	0.9479	0.9461	0.9443	0.9433	0.9479	0.9513	0.9539
240 0.9483 0.9464 0.9445 0.9426 0.9403 0.9464 0.9504 0.9533 300 0.9482 0.9463 0.9444 0.9425 0.9401 0.9463 0.9504 0.9533		180	0.9485	0.9466	0.9447	0.9429	0.9410	0.9466	0.9505	0.9534
			0.9483	0.9464	0.9445	0.9426	0.9403	0.9464	0.9504	0.9533
360 0.9482 0.9463 0.9444 0.9425 0.9400 0.9463 0.9504 0.9533		300	0.9482	0.9463	0.9444	0.9425	0.9401	0.9463	0.9504	0.9533
		360	0.9482	0.9463	0.9444	0.9425	0.9400	0.9463	0.9504	0.9533

- (a) the failure and repair rates of the crystallization subsystem (β_1, μ_1) and its standby unit (β_2, μ_2) are the same;
- (b) the failure and repair rates of the centrifugal pump subsystem (β_3, μ_3) and its standby units (β_4, μ_4) and (β_5, μ_5) are the same.

The fuzzy availability of the crystallization system is computed for 1 year (i.e., time, t=60–360 days). The

different choices of failure rate and repair rate of the subsystems at different values of coverage factor (c) are computed to observe their effect on the fuzzy availability of the system. The data regarding the failure and repair rates of all the subsystems are taken from the plant personnel as stated earlier in Sect. 2. The fuzzy availability of the system (A_F) is composed of fuzzy availability of the system working with full capacity and its standby states, i.e.,





Table 2 Effect of failure and repair rates of the centrifugal pump subsystem on the fuzzy availability of the system

System coverage factor (c)	Days	Failure rate of the centrifugal pump (β_3)				Repair rate of crystallization (μ_3)			
		0.0024	0.0025	0.0026	0.0027	0.037	0.042	0.047	0.052
c = 0	60	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335	0.7335
	120	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623	0.6623
	180	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433	0.6433
	240	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382	0.6382
	300	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369	0.6369
	360	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365	0.6365
c = 0.2	60	0.7715	0.7713	0.7712	0.7710	0.7709	0.7713	0.7717	0.7720
	120	0.7060	0.7058	0.7056	0.7055	0.7053	0.7058	0.7062	0.7066
	180	0.6868	0.6866	0.6864	0.6863	0.6861	0.6866	0.6870	0.6874
	240	0.6811	0.6809	0.6808	0.6806	0.6804	0.6809	0.6813	0.6817
	300	0.6794	0.6792	0.6791	0.6789	0.6787	0.6792	0.6796	0.6800
	360	0.6789	0.6787	0.6785	0.6784	0.6782	0.6787	0.6791	0.6795
c = 0.4	60	0.8124	0.8121	0.8117	0.8114	0.8112	0.8121	0.8128	0.8135
	120	0.7554	0.7551	0.7547	0.7544	0.7540	0.7551	0.7560	0.7567
	180	0.7372	0.7368	0.7365	0.7361	0.7357	0.7368	0.7377	0.7385
	240	0.7312	0.7309	0.7305	0.7302	0.7297	0.7309	0.7318	0.7326
	300	0.7293	0.7289	0.7286	0.7282	0.7278	0.7289	0.7299	0.7306
	360	0.7286	0.7283	0.7279	0.7276	0.7271	0.7283	0.7292	0.7300
c = 0.6	60	0.8566	0.8560	0.8555	0.8549	0.8547	0.8560	0.8572	0.8582
	120	0.8116	0.8111	0.8105	0.8099	0.8093	0.8111	0.8125	0.8137
	180	0.7961	0.7955	0.7949	0.7944	0.7936	0.7955	0.7970	0.7982
	240	0.7906	0.7900	0.7894	0.7889	0.7881	0.7900	0.7915	0.7927
	300	0.7886	0.7880	0.7874	0.7869	0.7861	0.7880	0.7895	0.7908
	360	0.7879	0.7873	0.7867	0.7862	0.7854	0.7873	0.7888	0.7900
c = 0.8	60	0.9042	0.9034	0.9027	0.9019	0.9015	0.9034	0.9051	0.9065
	120	0.8757	0.8749	0.8741	0.8732	0.8723	0.8749	0.8770	0.8788
	180	0.8655	0.8646	0.8638	0.8630	0.8619	0.8646	0.8668	0.8686
	240	0.8616	0.8607	0.8599	0.8591	0.8579	0.8607	0.8629	0.8647
	300	0.8600	0.8592	0.8584	0.8575	0.8564	0.8592	0.8614	0.8632
	360	0.8594	0.8586	0.8578	0.8569	0.8558	0.8586	0.8608	0.8626
c = 1.0	60	0.9557	0.9546	0.9536	0.9526	0.9521	0.9546	0.9568	0.9587
	120	0.9490	0.9479	0.9468	0.9456	0.9443	0.9479	0.9508	0.9532
	180	0.9478	0.9466	0.9455	0.9443	0.9428	0.9466	0.9497	0.9521
	240	0.9475	0.9464	0.9452	0.9441	0.9425	0.9464	0.9494	0.9519
	300	0.9474	0.9463	0.9451	0.9440	0.9424	0.9463	0.9494	0.9518
	360	0.9474	0.9463	0.9451	0.9440	0.9424	0.9463	0.9493	0.9518

$$A_{\rm F} = P_1 + \frac{1}{2} P_2 + \frac{1}{2} P_3 + \frac{1}{4} P_4 + \frac{1}{2} P_5 + \frac{1}{4} P_6.$$
(19)

Performance analysis of the system

In this section, the fuzzy availability of the system is computed using Eq. (19), and the effect of change in the failure and repair rates of subsystems and coverage factor (c) on the fuzzy availability of the system is presented in Tables 1, 2 and 3.

Effect of failure and repair rates of the crystallization subsystem on the fuzzy availability of the system

The effect of the failure rate of the crystallization subsystem on the fuzzy availability of the system is studied by varying their values as: $\beta_1 = 0.0011$, 0.0012, 0.0013 and 0.0014 at the repair rate (μ_1) 0.023 at different values of the coverage factor. The failure and repair rates of other subsystems were taken as: $\beta_3 = 0.0025$, $\beta_6 = 0.008$, $\beta_2 = \beta_1$,



Table 3 Effect of failure and repair rates of the sugar grader subsystem on the fuzzy availability of the system

System coverage factor (c)	Days	Failure ra	te of the suga	ar grader unit	(β_6)	Repair rate of the sugar grader unit (μ_6)				
		0.007	0.008	0.009	0.01	0.009	0.014	0.019	0.024	
c = 0	60	0.7612	0.7335	0.7071	0.6820	0.6991	0.7335	0.7623	0.7866	
	120	0.6935	0.6623	0.6335	0.6067	0.5906	0.6623	0.7153	0.7554	
	180	0.6743	0.6433	0.6149	0.5889	0.5515	0.6433	0.7060	0.7508	
	240	0.6688	0.6382	0.6103	0.5846	0.5374	0.6382	0.7042	0.7501	
	300	0.6673	0.6369	0.6091	0.5836	0.5323	0.6369	0.7038	0.7500	
	360	0.6668	0.6365	0.6088	0.5834	0.5304	0.6365	0.7037	0.7500	
c = 0.2	60	0.7950	0.7713	0.7486	0.7268	0.7424	0.7713	0.7955	0.8159	
	120	0.7336	0.7058	0.6798	0.6553	0.6430	0.7058	0.7519	0.7865	
	180	0.7147	0.6866	0.6605	0.6363	0.6037	0.6866	0.7423	0.7816	
	240	0.7088	0.6809	0.6551	0.6311	0.5881	0.6809	0.7402	0.7807	
	300	0.7070	0.6792	0.6535	0.6297	0.5819	0.6792	0.7397	0.7805	
	360	0.7064	0.6787	0.6531	0.6293	0.5795	0.6787	0.7396	0.7805	
c = 0.4	60	0.8311	0.8121	0.7937	0.7759	0.7893	0.8121	0.8311	0.8471	
	120	0.7783	0.7551	0.7330	0.7119	0.7033	0.7551	0.7927	0.8208	
	180	0.7608	0.7368	0.7142	0.6928	0.6663	0.7368	0.7835	0.8159	
	240	0.7550	0.7309	0.7083	0.6869	0.6502	0.7309	0.7812	0.8149	
	300	0.7530	0.7289	0.7064	0.6851	0.6431	0.7289	0.7806	0.8146	
	360	0.7523	0.7283	0.7058	0.6846	0.6400	0.7283	0.7804	0.8146	
c = 0.6	60	0.8695	0.8560	0.8428	0.8299	0.8401	0.8560	0.8694	0.8805	
	120	0.8284	0.8111	0.7943	0.7781	0.7731	0.8111	0.8385	0.8587	
	180	0.8139	0.7955	0.7779	0.7609	0.7419	0.7955	0.8304	0.8543	
	240	0.8087	0.7900	0.7721	0.7550	0.7270	0.7900	0.8282	0.8533	
	300	0.8067	0.7880	0.7701	0.7530	0.7199	0.7880	0.8276	0.8531	
	360	0.8060	0.7873	0.7694	0.7523	0.7164	0.7873	0.8274	0.8530	
c = 0.8	60	0.9107	0.9034	0.8963	0.8892	0.8869	0.8963	0.9041	0.9107	
	120	0.8846	0.8749	0.8653	0.8559	0.8421	0.8653	0.8820	0.8942	
	180	0.8753	0.8646	0.8542	0.8440	0.8202	0.8542	0.8760	0.8907	
	240	0.8717	0.8607	0.8500	0.8396	0.8091	0.8500	0.8743	0.8899	
	300	0.8703	0.8592	0.8484	0.8379	0.8033	0.8484	0.8738	0.8896	
	360	0.8697	0.8586	0.8478	0.8372	0.8003	0.8478	0.8736	0.8896	
c = 1.0	60	0.9546	0.9546	0.9546	0.9546	0.9546	0.9546	0.9546	0.9546	
	120	0.9479	0.9479	0.9479	0.9479	0.9479	0.9479	0.9479	0.9479	
	180	0.9466	0.9466	0.9466	0.9466	0.9466	0.9466	0.9466	0.9466	
	240	0.9464	0.9464	0.9464	0.9464	0.9464	0.9464	0.9464	0.9464	
	300	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	
	360	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	0.9463	

 $\beta_3 = \beta_4 = \beta_5$, $\mu_3 = 0.042$, $\mu_6 = 0.014$, $\mu_2 = \mu_1$, $\mu_3 = \mu_4 = \mu_5$. The fuzzy availability of the system is calculated using this data and the results are shown in Table 1 and presented in Fig. 3. This table shows that the fuzzy availability of the system decreases from 22.782 to 1.75 % approximately with the increase of time. However, it decreases by 0.6 % approximately with the increase in the failure rate of the crystallization subsystem approximately. Figure 3 shows that the rate of change in the fuzzy availability of the system increases with the increase in the

value of the system coverage factor (as $0 \le c \le 1$) and decreases with time.

The effect of the repair rate of the crystallization system on the fuzzy availability of the system is studied by varying their values as: $\mu_1 = 0.018, \ 0.023, \ 0.028$ and 0.033 at a failure rate of (β_1) 0.0012. The failure and repair rates of other subsystems have been taken as: $\beta_3 = 0.0025, \quad \beta_6 = 0.008, \quad \beta_2 = \beta_1, \quad \beta_3 = \beta_4 = \beta_5, \quad \mu_3 = 0.042, \quad \mu_6 = 0.014, \quad \mu_2 = \mu_1 \text{ and } \mu_3 = \mu_4 = \mu_5.$ The fuzzy availability of the system is calculated using this





Fig. 3 Effect of variation in the failure rate of crystallization subsystems on the fuzzy availability of the system




Fig. 4 Effect of variation in the failure rate of the centrifugal pump subsystem on the fuzzy availability of the system





Fig. 5 Effect of variation in the failure rate of the sugar grader subsystem on the fuzzy availability of the system



data and the results are shown in Table 1 and presented in Fig. 6. This table shows that the fuzzy availability of the system decreases from 1.523 to 22.782 % approximately with the increase of time. However, it increases by 1.412 % approximately with the increase in the repair rate of the crystallization system approximately. Figure 6 shows that the rate of change in fuzzy availability of the system decreases with the increase in the value of the system coverage factor (as $0 \le c \le 1$) and decreases with time.

The effect of failure and repair rates of the centrifugal pump subsystem on the fuzzy availability of the system

The effect of the failure rate of the centrifugal pump subsystem on the fuzzy availability of the system is studied by varying their values as $\beta_3 = 0.0024$, 0.0025, 0.0026 and 0.0027 at repair rate (μ_3) 0.042 at different values of the coverage factor. The failure and repair rates of the other subsystems have been taken as $\beta_1 = 0.0012$, $\beta_6 = 0.008$,



Fig. 6 Effect of variation in the repair rate of the crystallization subsystem on the fuzzy availability of the system




Fig. 7 Effect of variation in the repair rate of the centrifugal pump subsystem on the fuzzy availability of the system





Fig. 8 Effect of variation in the repair rate of the sugar grader subsystem on the fuzzy availability of the system



 $\beta_2=\beta_1,~~\beta_3=\beta_4=\beta_5,~~\mu_6=0.014,~~\mu_2=\mu_1~~{\rm and}~~\mu_3=\mu_4=\mu_5.$ The fuzzy availability of the system is calculated using this data and the results are shown in Table 2 and Fig. 4. This table shows that the fuzzy availability of the system decreases from 22.782 to 2.0 % approximately with the increase of time. However, it decreases by 0.364 % approximately with the increase in the failure rate of the centrifugal subsystem approximately. Figure 4 shows that the rate of change in the fuzzy availability of the system increases with the increase in the

value of the system coverage factor (as $0 \le c \le 1$) and decreases with time.

The effect of repair rate of the centrifugal system on the fuzzy availability of the system is studied by varying their values as $\mu_3 = 0.037$, 0.042, 0.047 and 0.52 at a failure rate of (β_3) 0.0025. The failure and repair rates of other subsystems have been taken as $\beta_1 = 0.0012$, $\beta_6 = 0.008$, $\beta_2 = \beta_1$, $\beta_3 = \beta_4 = \beta_5$, $\mu_1 = 0.023$, $\mu_6 = 0.014$, $\mu_2 = \mu_1$ and $\mu_3 = \mu_4 = \mu_5$. The fuzzy availability of the system is calculated using this data and the results are shown in Table 2





and Fig. 7. This table shows that the fuzzy availability of the system decreases from 1.748 to 22.782 % approximately with the increase of time. However, it increases by 0.364 % approximately with the increase in the repair rate of the centrifugal subsystem approximately. Figure 7 shows that the rate of change in fuzzy availability of the system decreases with the increase in the value of the system coverage factor (as $0 \le c \le 1$) and decreases with time.

Effect of failure and repair rates of the sugar grader subsystem on the fuzzy availability of the system

The effect of the failure rate of the sugar grader subsystem on the fuzzy availability of the system is studied by varying their values as $\beta_6 = 0.007$, 0.008, 0.009 and 0.01 at a repair rate (μ_6) 0.014 at different values of the coverage factor. The failure and repair rates of other subsystems have been taken as $\beta_1 = 0.0012$, $\beta_3 = 0.0025$, $\beta_2 = \beta_1$, $\beta_3 = \beta_4 = \beta_5$, $\mu_2 = \mu_1 = 0.023$ and $\mu_3 = \mu_4 = \mu_5 = 0.042$. The fuzzy availability of the system is calculated using this data and the results are shown in Table 3 and Fig. 5. This table shows that the fuzzy availability of the system decreases from 25.786 to 2.0 % approximately with the increase of time. However, it decreases by 6.878 to 12.512 % approximately with the increase in failure rate of the sugar grader subsystem approximately. Figure 5 shows that the rate of change in fuzzy availability of the system increases with the increase in the value of the system coverage factor (as 0 < c < 1) and decreases with time.

The effect of the repair rate of the sugar grader system on the fuzzy availability of the system is studied by varying their values as $\mu_6 = 0.009$, 0.014, 0.019 and 0.024 at a failure rate of (β_6) 0.008. The failure and repair rates of other subsystems have been taken as $\beta_1 = 0.0012$, $\beta_2 = \beta_1$, $\beta_3 =$ $\beta_4 = \beta_5 = 0.025$, $\mu_1 = 0.023$, $\mu_2 = \mu_1$ and $\mu_3 = \mu_4 =$ $\mu_5 = 0.042$. The fuzzy availability of the system is calculated using this data and the results are shown in Table 3 and Fig. 8. This table shows that the fuzzy availability of the system decreases from 2.1 to 34.672 % approximately with the increase of time. However, it increases by 12.664 % approximately with the increase in the repair rate of the sugar grader subsystem approximately. Figure 8 shows that the rate of change in the fuzzy availability of the system decreases with the increase in the value of the system coverage factor (as $0 \le c \le 1$) and decreases with time.

Conclusion

Analysis of fuzzy availability of crystallization system helps in increasing the production of sugar. The effects of coverage factor (c) corresponding to different values of failure and repair rates of all the subsystems are presented in Tables 1, 2 and 3 and shown graphically in Figs. 3, 4, 5, 6, 7 and 8. A comparative study concludes that the sugar grader subsystem has a prominent effect on the fuzzy availability of the system than that of other subsystems. The numeric results show that all the fuzziness, system coverage factor and maintenance have a significant effect on the fuzzy availability of the crystallization system. These results are presented and discussed with the plant personnel to adopt and practice suitable maintenance policies/strategies to enhance the performance of the crystallization system of the sugar plant.

Open Access This article is distributed under the terms of the Creative Commons Attribution 4.0 International License (http://creativecommons.org/licenses/by/4.0/), which permits unrestricted use, distribution, and reproduction in any medium, provided you give appropriate credit to the original author(s) and the source, provide a link to the Creative Commons license, and indicate if changes were made.

References

Arora N, Kumar D (1997)'Maintenance management and profit analysis of the system in a thermal power plant'. In: Proceeding of ICOQM

Balaguruswamy E (1984) Reliability engineering. Tata McGraw Hill, New Delhi

Biswas A, Sarkar J (2000) Availability of a system maintained through several imperfect repair before a replacement or a perfect repair. Stat Reliab Lett 50:105–114

Blischke WR, Murthy DNP (2003) Case studies in reliability and maintenance. Wiley, USA

Cai KY (1996) Introduction to fuzzy reliability. Kluwer Academic, Norwell. ISBN 0792397371

Chen SM (1994) Fuzzy system reliability analysis using fuzzy number arithmetic operations'. Fuzzy Sets Syst 64(1):31–38

Chen SM (2003) Analyzing fuzzy system reliability using vague set theory. Int J Appl Sci Eng 1(1):82–88

Cheng CH, Mon DL (1993) Fuzzy system reliability analysis by interval of confidence. Fuzzy Sets Syst 56(1):29–35

Dhillion BS, Singh C (1981) Engineering reliability: new techniques and applications. Wiley, New York

Dhople SV, DeVille L, Domínguez-García AD (2014) A stochastic hybrid systems framework for analysis of markov reward models. Reliab Eng Syst Saf 123(3):158–170

Doostparast M, Kolahan F, Doostparast M (2014) A reliability based approach to optimize preventive maintenance scheduling for coherent systems. Reliab Eng Syst Saf 1(6):98–106

Ebeling A (2001) An introduction to reliability and maintainability engineering. Tata McGraw Hill Company Ltd, New Delhi

Garg H, Sharma SP (2011) Multi-objective optimization of crystallization unit in a fertilizer plant using particle swarm optimization. Int J Appl Sci Eng 9(4):261–276

Garg H, Sharma SP (2012) Behavior analysis of synthesis unit in fertilizer plant. Int J Qual Reliab Manag 2:217–232

Jain M (2003) N-policy for redundant repairable system with additional repairman. OPSEARCH 40(2):97–114

Katherasan D, Jiju V, Elias P, Sathiya A, Haq N (2013) Modeling and optimization of flux cored arc welding by genetic algorithm and simulated annealing algorithm. Multidiscip Model in Mater Str 9(3):307–326



58 J Ind Eng Int (2017) 13:47–58

Knezevic J, Odoom ER (2001) Reliability modelling of repairable systems using petri nets and fuzzy lambda-tau methodology. Reliab Eng Syst Saf 73(1):1–17

- Kumar K, Kumar P (2011) Fuzzy availability modeling and analysis of biscuit manufacturing plant: a case study. Int J Syst Assur Eng Manag 2(3):193–204
- Kumar M, Yadav SP (2012) A novel approach for analyzing fuzzy system reliability using different types of intuitionistic fuzzy failure rates of components. ISA Trans 51(2):288–297
- Kumar A, Sharma SP, Kumar D (2007) 'Robot reliability using Petri nets and fuzzy lambda-tau methodology'. In: Proceeding of the 3rd International Conference on Reliability and Safety Engineering, Udaipur, pp 517–521
- Natarajan M, Natarajan V, Senthil SR, Devadasan N, Mohan V, Sivaram NM (2013) Quality and reliability in new product development: a case study in compressed air treatment products manufacturing company. J Manuf Technol Manag 24(8):1143–1162
- Ram M, Singh SB, Varshney RG (2013) Performance improvement of a parallel redundant system with coverage factor. J Eng Sci Technol 8(3):344–350
- Renganathan K, Bhaskar V (2011) An observer based approach for achieving fault diagnosis and fault tolerant control of systems modeled as hybrid Petri nets. ISA Trans 50(3):443–453
- Shakuntla M, Kalal S, Lal AK, Bhatia SS, Singh J (2011) Availability analysis of poly tube industry when two sub-system are simultaneous fail. Bangladesh J Sci Ind Res 46(4):475–480
- Sharma G, Khanduja R (2013) Performance evaluation and availability analysis of feeding system in a sugar industry. Int J Res Eng Appl Sci 3(9):38–50
- Singer D (1990) A fuzzy set approach to fault tree and reliability analysis. Fuzzy Sets Syst 34(2):145-155
- Singh DV, Tuteja R, Taneja G, Minocha A (2005) 'Analysis of a reliability model for an ash handling plant consisting of three pumps'. In: International Conference on Reliability and Safety Engineering, Indian Institute of Technology, Kharagpur, pp 465–472
- Taheri S, Zarei R (2011) Bayesian system reliability assessment under the vague environment. Appl Soft Comput 11(2):1614–1622

- You PS, Chen TC (2005) An efficient heuristic for series-parallel redundant reliability problems. Comput Oper Res 32:2117–2127
- Yuan Li, Meng XY (2011) Reliability analysis of a warm standby repairable system with priority in use. Appl Math Model 35:4295–4303
- Zadeh LA (1965) Fuzzy sets. Inform Control 8:338-353
- Zhang Chi, Mostashari Ali (2011) Influence of component uncertainty on reliability assessment of systems with continuous states. Int J Ind Syst Eng 7(4):542–552
- Zoulfaghari H, Hamadani AZ, Ardakan MA (2014) Bi-objective redundancy allocation problem for a system with mixed repairable and non-repairable components. ISA Trans 53(1):17–24
- Anil Kr. Aggarwal is a research scholar in mechanical engineering from YMCA University of Science & Technology, Faridabad (India). He received his B.E. (Mech.) from Jamia Millia Islamia, New Delhi (India). He received his M.Tech. (Production) from GNDEC, Ludhiana, Punjab. He has 14 years of teaching experience and published papers in international/national journals and conferences.
- Sanjeev Kumar is Associate Professor in the Department of Mechanical Engineering at YMCA University of Science & Technology, Faridabad (India). He received his Ph.D. in industrial engineering from the National Institute of Technology, Kurukshetra, Haryana (India). He has 15 years of experience in teaching and research. He has published and presented about 40 research papers in international and national journals/conferences.
- Vikram Singh is Associate Professor in the Department of Mechanical Engineering at YMCA University of Science & Technology, Faridabad (India). He received his B.Tech. (Mech.) from REC Kurukshetra (presently known as NIT Kurukshetra). He received his M.E. (Mech.) from the Punjab Engineering College, Punjab (India). He received his Ph.D. in mechanical engineering from the M.D. University, Rohtak, Haryana (India). He has 15 years of experience in teaching and research. He has published and presented about 30 research papers in international and national journals/conferences.